

**Appendix 5: Magoon (1962) observations of the 1964 tsunami in San Francisco Bay**

Location	Site	Lat (°N)	Lon (°W)	No.	Water Elevation above MLLW (m)	Max. Wave Height (m)	Time of Water Max (PST)	Damage (\$, 1964)	Remarks
San Francisco	Presidio/Golden Gate	37.8	122.45	A	2.6	2.3	1:00	None	tide gage
Sausalito	Bauman Bros. Sales	37.86	122.48	16			1:30	None	
Sausalito	Marinship Yacht Harbor	37.87	122.5	18	1.7	1.2	2:00	None	
Sausalito	Clipper Yacht Harbor	37.87	122.5	19		1.2	2:00	100000	Damage to floating structures & boats
Belvedere	SF Yacht Club	37.87	122.46	22		1.5	2:00	None	
San Rafael	San Rafael Yacht Harbor	37.96	122.51	31	2.4			7500	Damage to floating structures & boats
San Rafael	Lowries Yacht Harbor	37.97	122.49	36	2.0	1.5	2:00	10000	Damage to floating structures & boats
San Rafael	Loch Lomond Harbor	37.98	122.47	39				60000	One boat broke loose damaging other boats/facilities
Vallejo	Mare Isl. Naval Shipyard	38.1	122.27	G	0.2			None	tide gage
Vallejo	Glen Cove Harbor	38.09	122.25	103		slight		None	Fish stopped biting
Benicia	Benicia	38.07	122.45			0.1		None	
Suisin	Paul's Yacht Harbor	38.11	122.07	105	not observed			None	
Antioch	Big Break Resort	38.02	121.73	52	not observed			None	
Antioch	Lauritzen Yacht Harbor	38.02	121.75	53	not observed			None	
Antioch	Bridge Marina	38.02	121.76	55	not observed			None	
Antioch	San Joaquin Yacht Harbor	38.02	121.76	57	not observed			None	
Pittsburg	Pittsburg Marina	38.07	121.89	107	not observed			None	
McAvoy	Harris Yacht Club	38.05	121.95	59	not observed			None	
Crockett	Eckley's Resort	38.05	122.2	62	not observed			None	
Crockett	Dowrelio's Harbor	38.06	122.23	63	not observed			None	
Rodeo	Rodeo Marina	38.04	122.27	64	not observed			None	
Pt. San Pablo	Standard Oil Co.	37.96	122.41	66	2.3	1.3	1:50	None	Oscillations on gage for 10 days

Borrero et al., Numerical Modeling of Tsunami Effects at Marine Oil Terminals in San Francisco Bay  
Appendix 5: Magoon (1962) observations of the 1964 tsunami in San Francisco Bay.

Pt. San Pablo	Pt. San Pablo Yacht Harbor	37.96	122.42	65	1.7	1.9	2:00	None	Like fast tidal currents
Pt. Richmond	Red Rock Marina	37.93	122.4		2.1		after 1:30	None	Boats touch bottom
Richmond	Richmond Yacht Service	37.92	122.37	67	1.8	0.5		None	
Richmond	Richmond Yacht Harbor	37.92	122.37	68	≥1.8	2.1		None	Low water to -1 MLLW
Richmond	Channel Marina	37.91	122.36	70	≥1.8	2.7		slight	Low water to -1 MLLW
Berkeley	Berkeley Yacht Harbor	37.87	122.32	71			2:40	100	
Oakland	Norwalk Yacht Harbor	37.8	122.3	72	2.0	2.3	1:45	None	
Oakland	Jack London Marina	37.8	122.27	112	1.8	2.1		None	
Oakland	Embarcadero Yacht Harbor	37.79	122.26		1.8	2.4		None	
Oakland	Oakland Marina	37.79	122.26	77	2.1			None	
Oakland	Lani Kai Harbor	37.79	122.26	81	0.6			None	
Alameda	Pacific Marina	37.78	122.27	74	not observed			None	
Alameda	Alameda Yacht Club	37.78	122.26	73	not observed			None	
Alameda	Aeolian Yacht Club	37.75	122.23	84	not observed			None	
San Leandro	San Leandro Marino	37.7	122.19	115	not observed			None	
Alviso	Alviso Marina	37.4	122.01	117	not observed			None	
Palo Alto	Palo Alto Yacht Harbor	37.45	122.08	2	not observed			None	
Redwood City	Redwood City Muni	37.5	122.21	4	not observed			None	
Redwood City	Redwood Marina	37.49	122.22	3	not observed			None	
Redwood City	Pete's Harbor	37.5	122.22	5	not observed			None	
Burlingame	Coyote Point Harbor	37.59	122.24	8	not observed			None	
S. San Francisco	Oyster Point Harbor	37.68	122.38	118	not observed			None	
Alviso	Entrance to Alviso Slough	37.46	122.03	C		0.3		None	tide gage
Alameda	Naval Air Station, Alameda	37.79	122.32	D		1.6		None	tide gage
Richmond	Standard Oil Co.	37.92	122.39	F	2.3	1.2		None	tide gage
Benicia	Benicia Harbor	38.04	122.14	H		0.1		None	tide gage